

**Inspection Photo
Federal RWF 342-19
API # 045-10097
Inspection # 689301566**



Location Photo #1



Location Photo #2, debris on East end of Battery.

**Inspection Photo
Federal RWF 342-19
API # 045-10097
Inspection # 689301566**



**Location Photo #3, Holes in containment liner
near stairs.**