

**Inspection Photo
Federal RMV 63-19
API # 045-07028
Inspection # 689301568**



Location Photo #1



**Location Photo #2, hole in perimeter ditch,
East side of location near trees.**

**Inspection Photo
Federal RMV 63-19
API # 045-07028
Inspection # 689301568**



Location Photo #3, hole in perimeter ditch

Location Photo #4, hole in perimeter ditch