

Inspection Photo
Circle B Land 44C-35-692
API # 045-12380
Inspection # 689301584



Location Photo #1



Location Photo #2

Inspection Photo
Circle B Land 44C-35-692
API # 045-12380
Inspection # 689301584



Location Photo #3



Location Photo #4



Inspection Photo
Circle B Land 44C-35-692
API # 045-12380
Inspection # 689301584



**Location Photo #5, Stained material in
compressor containment**



**Location Photo #6, Stained material in
compressor containment**

Inspection Photo
Circle B Land 44C-35-692
API # 045-12380
Inspection # 689301584



**Location Photo #7, Containers not labeled
near compressor**



**Location Photo #8, Missing information on
tanks**

Inspection Photo
Circle B Land 44C-35-692
API # 045-12380
Inspection # 689301584



**Location Photo #9, Containers not labeled
near 400 bbl tanks**



**Location Photo #10, Stained material in
containment area.**