

Inspection Photo
Circle B Land 11A-35-692
API # 045-14303
Inspection # 689301592



Location Photo #1

Location Photo #2

Inspection Photo
Circle B Land 11A-35-692
API # 045-14303
Inspection # 689301592



Location Photo #3, Stained material in battery containment

Location Photo #4, stained material in battery containment

Inspection Photo
Circle B Land 11A-35-692
API # 045-14303
Inspection # 689301592



Location Photo #5, Battery sign non legible