

Inspection Photos

Location Name: Croissant - 69N62W / 26NWNW

Location #: 331970



Photo #1

Croissant #4 (API # 05-123-21651) wellsite

No sign or emergency contact info posted



Photo #2

Croissant #1 (API # 05-123-21426),

Croissant #4 (API # 05-123-21651),

Graefe #1 (API # 05-123-06129)

Debris at Battery



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Croissant - 69N62W / 26NWNW

Location #: 331970



Photo #3

Croissant #1 (API # 05-123-21426),
Croissant #4 (API # 05-123-21651),
Graefe #1 (API # 05-123-06129)
Battery site



Photo #4

Croissant #1 (API # 05-123-21426),
Croissant #4 (API # 05-123-21651),
Graefe #1 (API # 05-123-06129)
Unused equipment

Inspection Photos

Location Name: Croissant - 69N62W / 26NWNW

Location #: 331970



Photo #5

Croissant #1 (API # 05-123-21426),
Croissant #4 (API # 05-123-21651),
Graefe #1 (API # 05-123-06129)

Unused equipment



Photo #6

Croissant #1 (API # 05-123-21426),
Croissant #4 (API # 05-123-21651),
Graefe #1 (API # 05-123-06129)

Unused equipment



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Croissant - 69N62W / 26NWNW

Location #: 331970



Colorado Oil & Gas Conservation Commission
40.72213, -104.29473, 1507.0m, 296°
2018/07/20 12:42:40 PM

Photo #7

Croissant #1 (API # 05-123-21426),

Croissant #4 (API # 05-123-21651),

Graefe #1 (API # 05-123-06129)

Unused equipment



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources