

Inspection Photos

Location Name: Graefe - 69N62W / 26SWNW

Location #: 317527



Photo #1

Graefe #1 (API # 05-123-06129) wellsite

No sign or emergency contact info posted



Photo #2

Croissant #1 (API # 05-123-21426),

Croissant #4 (API # 05-123-21651),

Graefe #1 (API # 05-123-06129)

Debris at Battery



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Graefe - 69N62W / 26SWNW

Location #: 317527



Photo #3

Croissant #1 (API # 05-123-21426),
Croissant #4 (API # 05-123-21651),
Graefe #1 (API # 05-123-06129)
Battery site



Photo #4

Croissant #1 (API # 05-123-21426),
Croissant #4 (API # 05-123-21651),
Graefe #1 (API # 05-123-06129)
Unused equipment

Inspection Photos
Location Name: Graefe - 69N62W / 26SWNW
Location #: 317527



Photo #5

Croissant #1 (API # 05-123-21426),
Croissant #4 (API # 05-123-21651),
Graefe #1 (API # 05-123-06129)

Unused equipment



Photo #6

Croissant #1 (API # 05-123-21426),
Croissant #4 (API # 05-123-21651),
Graefe #1 (API # 05-123-06129)

Unused equipment



Inspection Photos

Location Name: Graefe - 69N62W / 26SWNW

Location #: 317527



Photo #7

Croissant #1 (API # 05-123-21426),

Croissant #4 (API # 05-123-21651),

Graefe #1 (API # 05-123-06129)

Unused equipment



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources