

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/24/2018

Submitted Date:

07/24/2018

Document Number:

689301592**FIELD INSPECTION FORM**

Loc ID 335001	Inspector Name: Holtz, Darin	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 18 Number of Comments 2 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested																																																							
Operator Information: OGCC Operator Number: <u>10531</u> Name of Operator: <u>VANGUARD OPERATING LLC</u> Address: <u>5847 SAN FELIPE #3000</u> City: <u>HOUSTON</u> State: <u>TX</u> Zip: <u>77057</u>																																																											
Contact Information: <table border="1"> <thead> <tr> <th>Contact Name</th> <th>Phone</th> <th>Email</th> <th>Comment</th> </tr> </thead> <tbody> <tr> <td>Aaron, Axelson</td> <td>230-0926</td> <td>aaxelson@vnrenergy.com</td> <td>Sr. Production Foreman</td> </tr> <tr> <td>Ghan, Scott</td> <td>970-744-8128</td> <td>sghan@vnrenergy.com</td> <td>SR. EH&S</td> </tr> </tbody> </table>					Contact Name	Phone	Email	Comment	Aaron, Axelson	230-0926	aaxelson@vnrenergy.com	Sr. Production Foreman	Ghan, Scott	970-744-8128	sghan@vnrenergy.com	SR. EH&S																																											
Contact Name	Phone	Email	Comment																																																								
Aaron, Axelson	230-0926	aaxelson@vnrenergy.com	Sr. Production Foreman																																																								
Ghan, Scott	970-744-8128	sghan@vnrenergy.com	SR. EH&S																																																								
Inspected Facilities: <table border="1"> <thead> <tr> <th>Facility ID</th> <th>Type</th> <th>Status</th> <th>Status Date</th> <th>Well Class</th> <th>API Num</th> <th>Facility Name</th> <th>Insp Status</th> </tr> </thead> <tbody> <tr> <td>291094</td> <td>WELL</td> <td>PR</td> <td>11/10/2008</td> <td>GW</td> <td>045-14303</td> <td>CIRCLE B LAND 11A-35-692</td> <td>PR</td> </tr> <tr> <td>291095</td> <td>WELL</td> <td>PR</td> <td>11/08/2008</td> <td>GW</td> <td>045-14302</td> <td>CIRCLE B LAND 11D-35-692</td> <td>PR</td> </tr> <tr> <td>291097</td> <td>WELL</td> <td>PR</td> <td>11/12/2008</td> <td>GW</td> <td>045-14301</td> <td>CIRCLE B LAND 12C-35-692</td> <td>PR</td> </tr> <tr> <td>291099</td> <td>WELL</td> <td>PR</td> <td>11/05/2008</td> <td>GW</td> <td>045-14300</td> <td>CIRCLE B LAND 12B-35-629</td> <td>PR</td> </tr> <tr> <td>294937</td> <td>WELL</td> <td>PR</td> <td>11/14/2008</td> <td>GW</td> <td>045-15639</td> <td>CIRCLE B LAND 13D-35-692</td> <td>PR</td> </tr> <tr> <td>294938</td> <td>WELL</td> <td>PR</td> <td>11/04/2008</td> <td>GW</td> <td>045-15638</td> <td>CIRCLE B LAND 11B-35-692</td> <td>PR</td> </tr> </tbody> </table>				Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	291094	WELL	PR	11/10/2008	GW	045-14303	CIRCLE B LAND 11A-35-692	PR	291095	WELL	PR	11/08/2008	GW	045-14302	CIRCLE B LAND 11D-35-692	PR	291097	WELL	PR	11/12/2008	GW	045-14301	CIRCLE B LAND 12C-35-692	PR	291099	WELL	PR	11/05/2008	GW	045-14300	CIRCLE B LAND 12B-35-629	PR	294937	WELL	PR	11/14/2008	GW	045-15639	CIRCLE B LAND 13D-35-692	PR	294938	WELL	PR	11/04/2008	GW	045-15638	CIRCLE B LAND 11B-35-692	PR
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status																																																				
291094	WELL	PR	11/10/2008	GW	045-14303	CIRCLE B LAND 11A-35-692	PR																																																				
291095	WELL	PR	11/08/2008	GW	045-14302	CIRCLE B LAND 11D-35-692	PR																																																				
291097	WELL	PR	11/12/2008	GW	045-14301	CIRCLE B LAND 12C-35-692	PR																																																				
291099	WELL	PR	11/05/2008	GW	045-14300	CIRCLE B LAND 12B-35-629	PR																																																				
294937	WELL	PR	11/14/2008	GW	045-15639	CIRCLE B LAND 13D-35-692	PR																																																				
294938	WELL	PR	11/04/2008	GW	045-15638	CIRCLE B LAND 11B-35-692	PR																																																				

Contact Name	Phone	Email	Comment
Aaron, Axelson	230-0926	aaxelson@vnrenergy.com	Sr. Production Foreman
Ghan, Scott	970-744-8128	sghan@vnrenergy.com	SR. EH&S

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
291094	WELL	PR	11/10/2008	GW	045-14303	CIRCLE B LAND 11A-35-692	PR
291095	WELL	PR	11/08/2008	GW	045-14302	CIRCLE B LAND 11D-35-692	PR
291097	WELL	PR	11/12/2008	GW	045-14301	CIRCLE B LAND 12C-35-692	PR
291099	WELL	PR	11/05/2008	GW	045-14300	CIRCLE B LAND 12B-35-629	PR
294937	WELL	PR	11/14/2008	GW	045-15639	CIRCLE B LAND 13D-35-692	PR
294938	WELL	PR	11/04/2008	GW	045-15638	CIRCLE B LAND 11B-35-692	PR

General Comment:
[Routine Field Inspection](#)

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:	Sign not legible, see photo		
Corrective Action:	Install sign to comply with Rule 210.e.	Date:	09/24/2018

Emergency Contact Number:

Comment: 1-800-921-8252

Corrective Action:

Date:

Good Housekeeping:			
Type	OTHER		
Comment:	Stained material in containment battery, see photo		
Corrective Action:	Properly treat or dispose of oily waste in accordance with Rule 907.e.	Date:	08/24/2018

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:	livestock gates		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Livestock gates		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 6		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 6		

Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Chemical units at Separators		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 6		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	500 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	STEEL AST		,
Comment:	Blow down tank at Wellhead				
Corrective Action:					
					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Inspector Name: Holtz, Darin

Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	500 BBLs	HEATED STEEL AST		,
Comment:	Centralized battery				
Corrective Action:					Date:
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Venting:					
Yes/No	YES				
Comment:	Bradenheads open				
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities									
Facility ID:	291094	Type:	WELL	API Number:	045-14303	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	291095	Type:	WELL	API Number:	045-14302	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	291097	Type:	WELL	API Number:	045-14301	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	291099	Type:	WELL	API Number:	045-14300	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	294937	Type:	WELL	API Number:	045-15639	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	294938	Type:	WELL	API Number:	045-15638	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				
Seeding						
Gravel				Material Handling And Spill Prevention		
Berms						
		Gravel				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689301593	Inspection photo 689301593	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4531828