

Inspection Photos
Location Name: Maloney 2-16
Location ID: 320269



Photo#1 Production tank and produced water pit



Photo#2 Equipment/Unused equipment

Inspection Photos
Location Name: Maloney 2-16
Location ID: 320269



Tuesday, July 24, 2018 09:22:10
15055 Tejon St Broomfield CO 80023
United States

Photo#3 Wellhead/Unused equipment

