

Inspection Photos
Location Name: ANDERSON TRUST 1
Facility ID: 241711



Photo 1. Wellhead



Photo 2. Weeds around wellhead

Inspection Photos
Location Name: ANDERSON TRUST 1
Facility ID: 241711



Photo 3. Weeds near crude oil tank



Photo 4. Weeds near separator