

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/26/2018

Submitted Date:

07/26/2018

Document Number:

692600030

**FIELD INSPECTION FORM**

Loc ID 438410 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**  
 THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**  
 OGCC Operator Number: 10489  
 Name of Operator: AUGUSTUS ENERGY RESOURCES LLC  
 Address: 2016 GRAND AVENUE #A  
 City: BILLINGS State: MT Zip: 59102

**Findings:**  
13 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Jones, Greg	(970) 332-3585	gjones@augustusenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
438408	WELL	PR	09/02/2014	GW	125-12103	McCall 42-09 1N46W	PR

**General Comment:**  
Routine Inspection

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Two track through pasture		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Lease sign mounted to fence at meter shed. Update to current operator		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Lease sign mounted to fence at unit		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	Metal panels around unit and wellhead		
Corrective Action:			Date:
Type	LOCATION		
Comment:	Wire fence around entire location		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Metal panels around VGS and meter shed		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Pump Jack	# 1		corrective date
Comment:	Jensen unit		
Corrective Action:			Date:
Type: Vertical Separator	# 2		
Comment:	2-Vertical gas separators 50% buried by meter shed 840' south		
Corrective Action:			Date:

Type: Ancillary equipment	# 2		
Comment:	Electric panel and telemetry equipment at meter shed		
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:			Date:
Type: Gas Meter Run	# 2		
Comment:	Shared meter run for McCall 42-09 and 43-09 840' south		
Corrective Action:			Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 438408 Type: WELL API Number: 125-12103 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing. Casing production. Central meter run for \(McCall 42-09 and 43-09\) 840' south of wellhead @ 40.06737/-102.51198](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT