

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401716381

Date Received:
07/26/2018

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 3 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Tesla Dougherty

907-304-5245

Tesla.dougherty@nblenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 684905506

Inspection Date: 06/12/2018

FIR Submit Date: 06/12/2018

FIR Status: _____

Inspected Operator Information:

Company Name: NOBLE ENERGY INC

Company Number: 100322

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

LOCATION - Location ID: 327025

Location Name: LILLI UNIT-68N58W Number: 6NWSW County: WELD

Qtrqr: NWS Sec: 6 Twp: 8N Range: 58W Meridian: 6

Latitude: 40.688660 Longitude: -103.912120

FACILITY - API Number: 05-123-00 Facility ID: 246226

Facility Name: LILLI UNIT Number: 12-6

Qtrqr: NWS Sec: 6 Twp: 8N Range: 58W Meridian: 6

Latitude: 40.688660 Longitude: -103.912120

CORRECTIVE ACTIONS:

1 CA# 116744

Corrective Action: Comply with rule 603.f.

Date: 06/22/2018

Response: CA COMPLETED

Date of Completion: 07/23/2018

Operator Comment: Noble has removed the weeds in the tank battery

COGCC Decision: _____

[illegible]

Date: 7/26/2018 3:38:47 PM

Page 2 of 2