



00047418

ADO OIL & GAS CONSERVATION COMMISSION
FIELD INSPECTION REPORT☐ NOTICE OF UNSATISFACTORY INSPECTION☒ NOTICE OF SATISFACTORY INSPECTION1120 Lincoln Street, Suite 801
Denver, CO 80203
(303)894-2100

API No. 05- 121 - 8082

LEASE NAME: Harpham 1

LOCATION: NWSE 3-2N-52W

OPERATOR: Doherty

DATE: 11-28-95

INSPECTOR: Binkley

Insp. Type: CA

Insp. Status: PA

PA: Y

☒ N

Pass/Fail: P

☒ F

Viol.: Y

☒ N

NOV: Y

☒ N

INSPECTION ITEM

COMMENTS

INPUT

Well ID Signs (Rule 210)	✓	
Pits (Reserve/Production) (Rule 902, 903, 904)	Smaller work pit used to cure water and cement.	
Fences (Rule 604.C.(3), 1003.A)		
Tank Battery Equipment (Rule 604)		
Fire Walls/Berms/Dikes (Rule 604)		
General Housekeeping (Rule 603.G)	ok, wheat field - fallow.	
Spills (Oil/Water) (Rule 908)		
Bradenhead (Rule 207)		
Drilling Well/Workover (Rule 315)	Donnelly Rig w/ Akron Cement - pumped 303x Realy mix @ 3710'	
Surface Rehabilitation (Rule 317)	at top of fish. Plans now to cure casing, cutoff at free point and set additional stub plug,	
Miscellaneous	shot plug and top plug - Thur/Frid.	

CORRECTIVE ACTION REQUIRED:

Date Corrective Action Required By:

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.

White - File Green - Operator Canary - Well Site