

Inspection Photos
Location Name: PACE CONOLLY #1
Facility ID: 241522



Colorado Oil & Gas Conservation Commission
40.1078, -104.97249, 1519.0m, 249°
2018/07/30 12:39:13

Photo 1. Wellhead Corrective actions: **Control weeds at wellhead and lease road. Remove unused equipment (pumping unit).**



Colorado Oil & Gas Conservation Commission
40.10284, -104.97762, 1496.0m, 351°
2018/07/30 12:55:52

Photo 2. Tank battery Corrective actions: **Control weeds around Tank battery.**

Inspection Photos
Location Name: PACE CONOLLY #1
Facility ID: 241522



Photo 3. Trash from previous inspection has been removed



Photo 4. Separator **Corrective actions: Control weeds around Headed separator.**

Inspection Photos
Location Name: PACE CONOLLY #1
Facility ID: 241522



Photo 5. ECD Corrective actions: Control weeds at ECD.

