

**Inspection Photo
Federal RWF 513-19
API # 045-10077
Inspection # 689301580**



Location Photo #1



Location Photo #2, missing wildlife screen

**Inspection Photo
Federal RWF 513-19
API # 045-10077
Inspection # 689301580**



Location Photo #3, Missing wellhead information on new proposed wells



Location Photo #4, Missing wellhead information on new proposed wells

**Inspection Photo
Federal RWF 513-19
API # 045-10077
Inspection # 689301580**



**Location Photo #5, Missing wellhead
information on new proposed wells**



**Location Photo #6, Missing wellhead
information on new proposed wells**

**Inspection Photo
Federal RWF 513-19
API # 045-10077
Inspection # 689301580**



Location Photo #7, Pit



Location Photo #8, Pit



**Inspection Photo
Federal RWF 513-19
API # 045-10077
Inspection # 689301580**



Location Photo #9, Missing tank information



Location Photo #10, missing wellhead information on existing wells.