

Inspection Photos
Location Name: Denali 15-12
API: 05-081-06967



Photo 1. Overview of location taken at entrance facing west.

Inspection Photos
Location Name: Denali 15-12
API: 05-081-06967



Photo 2. Unused tanks stored on location.



Photo 3. Battery sign at entrance knocked over.