

**BOSELY SG 43-22**  
**Api# 05-045-07243**  
**Inspection # 689701622**



**Location photo**

**BOSELY SG 43-22**  
**Api# 05-045-07243**  
**Inspection # 689701622**



**Tank volume not legible.**

**BOSELY SG 43-22**  
**Api# 05-045-07243**  
**Inspection # 689701622**



**Not repaired from previous inspection.**  
**Just before location washing of road cutting into v ditch. 39.42140 108.08775.**



**BOSELY SG 43-22**  
**Api# 05-045-07243**  
**Inspection # 689701622**



**Sediment build up behind berm.**

**BOSELY SG 43-22**  
**Api# 05-045-07243**  
**Inspection # 689701622**



**Channeling through location berm.**