

## Inspection Photos

Location Name: Sitzman 1 API: 05-123-11421, Spill ID 454307, Remediation #11252

Inspection Date: 7/31/2018



**Photo 1 – Excavated area from west side of excavated area looking northeast.**



**Photo 2 – Hydrogen peroxide tanker remains on location.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: Sitzman 1 API: 05-123-11421, Spill ID 454307, Remediation #11252

Inspection Date: 7/31/2018



**Photo 3 – Treatment area and excavated area from south end looking north.**



**Photo 4 – Excavated area from north end of excavation area looking south.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: Sitzman 1 API: 05-123-11421, Spill ID 454307, Remediation #11252

Inspection Date: 7/31/2018



**Photo 5 – Excavated area from northeast corner looking west-southwest.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources