



**Photo 1. View of the reclaimed well pad area from the southeastern corner facing center. Location is revegetated.**





**Photo 2. View of the eastern portion of the project area from the southeastern corner facing northward. Fence and wood debris in place. Weeds appear to be controlled at this time.**





**Photo 3. View of the southern portion of the project area from the southeastern corner facing westward.**





**Photo 4. View of pipe in southwestern corner that needs to be removed.**





**Photo 5. View of two track access road that needs to be reclaimed. Access is approximately 1480 feet from turnoff at fenceline road.**