

Inspection Photo
Overacker Federal 20-15B
API # 045-12429
Inspection # 689301632



Location Photo #1



Location Photo #1



**Inspection Photo
Overacker Federal 20-15B
API # 045-12429
Inspection # 689301632**



Location Photo #3, stained rock in battery containment.



Location Photo #4, Stained rock in battery containment.

**Inspection Photo
Overacker Federal 20-15B
API # 045-12429
Inspection # 689301632**



Location Photo #5, Stained rock in battery containment.



Location Photo #6, Stained rock in battery containment.