

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/01/2018

Submitted Date:

08/01/2018

Document Number:

692600050

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10112
 Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC
 Address: 5057 KELLER SPRINGS RD STE 650
 City: ADDISON State: TX Zip: 75001

Findings:

8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Beard, Alyssa		regulatory@foundationenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
252553	WELL	PR	10/01/2017	GW	125-06429	STULP 1-11	PR

General Comment:

[Routine Inspection](#)

Location

Lease Road:			
Type	Access		
comment:	Two track through pasture		
Corrective Action:		Date:	

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign by meter shed		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>		Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Wire fence around meter shed and metal shed		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	Telemetry equipment		
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:	1-Meter run for Stulp 1-11 1-Abandoned meter run		
Corrective Action:		Date:	
Type: Vertical Separator	# 4		
Comment:	1-Vertical gas separator in metal shed with wellhead 1-Vertical gas separator 50% buried by meter shed for Stulp 1-11 1-Vertical gas separator 50% buried by meter shed for abandoned meter run 1-Vertical gas separator 50% buried on west side of access for abandoned flowline		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 252553 Type: WELL API Number: 125-06429 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Casing production](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT