

Inspection Photos

08/02/2018

Operator: PCR OPERATING LLC - 10657

Location ID: 313768

Inspection Doc. Number: 682503692

Morgan County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: PCR OPERATING LLC - 10657
Location ID: 313768



Photo 1: Photo taken from the southwest corner of the location, facing north. Photo shows 1 of the 4 anchors that remain on the location.



Photo 2: Photo taken from the location. Photo shows pipe riser has not been removed from the location per corrective actions.

Inspection Photos
Operator: PCR OPERATING LLC - 10657
Location ID: 313768



Photo 3: Photo taken from the location. Photo shows gravel and road base remains on location. Note: Though location appears to be green and vegetated, vegetation seen on location is predominantly undesirable weedy plant species, or annual forbs. Very little desirable perennial vegetative establishment observed.



Photo 4: Photo taken from the location facing north. Photo shows that though location appears to be green and vegetated, vegetation seen on location is predominantly undesirable weedy plant species, or annual forbs. Very little desirable perennial vegetative establishment observed.



Photo 5: Photo of vegetation on location. Vegetation seen on location is predominantly undesirable weedy plant species, or annual forbs. Very little desirable perennial vegetative establishment observed