

Inspection Photos

08/02/2018

Operator: PCR OPERATING LLC - 10657

Location ID: 313755

Inspection Doc. Number: 682503694

Morgan County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: PCR OPERATING LLC - 10657
Location ID: 313755



Photo 1: Photo taken from the west end of the location, facing east. Previous inspections required operator to perform reclamation on the location and access road including, but not limited to, compaction alleviation, recontour/regrade and establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of pre-disturbance or reference area levels. Unable to find evidence that additional reclamation activities have been conducted. Location and access road remains predominantly vegetated by undesirable weedy plant species, or remains bare and exposed soil.



Photo 2: Photo taken from the west end of the location facing northeast. See comments under photo 1.

Inspection Photos
Operator: PCR OPERATING LLC - 10657
Location ID: 313755



Photo 3: Photo taken from the location. See comments under photo 1.



Photo 4: Photo taken from the south end of the location, facing south. Photo of access road. See comments under photo 1.