

Inspection Photos

08/02/2018

Operator: PETRO-CANADA RESOURCES (USA)
INC - 72085

Location ID: 311698

Inspection Doc. Number: 682503701
Adams County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: PETRO-CANADA RESOURCES (USA) INC - 72085
Location ID: 311698



Photo 1: Photo taken from the west of the location, facing north. Photo shows additional reclamation activities has been conducted within the drainage.



Photo 2: Photo taken from the west of the location, facing east. Photo shows additional reclamation activities has been conducted within the drainage.

Inspection Photos
Operator: PETRO-CANADA RESOURCES (USA) INC - 72085
Location ID: 311698



Photo 3: Photo taken from the access road, north of the location. Photo shows additional reclamation activities has been conducted



Photo 4: Photo taken from the access road, north of the location. Photo shows additional reclamation activities has been conducted

Inspection Photos
Operator: PETRO-CANADA RESOURCES (USA) INC - 72085
Location ID: 311698



Photo 5: Photo taken from the southern end of the drainage (east end of the disturbance), facing north. Photos 5-7 provide an overview of the reclamation work conducted within the drainage from north, northwest to west.



Photo 6:

Inspection Photos
Operator: PETRO-CANADA RESOURCES (USA) INC - 72085
Location ID: 311698



Photo 7:



Photo 8: Photo taken from the east end of the fenced disturbance area, facing northwest. Photo shows reclamation work conducted. Disturbed areas appear to have been re-contoured/regraded. Erosion control blankets have been implemented and appear to have been installed in accordance to good engineering practices. Straw wattles have been installed on sections of the perimeter.

Inspection Photos
Operator: PETRO-CANADA RESOURCES (USA) INC - 72085
Location ID: 311698



Photo 9: Photo taken from the east end of the fenced disturbance area, facing west. See comments under photo 8.



Photo 10: Photo taken from the south end of the fenced disturbance area, facing west. See comments under photo 8.