

# Inspection Photos

08/02/2018

Operator: PETRO-CANADA RESOURCES (USA)

INC - 72085

Location ID: 311680

Inspection Doc. Number: 682503704

Adams County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

## Inspection Photos

Operator: PETRO-CANADA RESOURCES (USA) INC - 72085

Location ID: 311680



**Photo 1:** Photo taken from the southwest of the location, facing north. Photo shows vegetation on location appears to be progressing, and stormwater and erosion control BMPs appear to be in proper functioning condition.



**Photo 2:** Photo taken from the southwest of the location, facing north. Photo shows vegetation on location appears to be progressing, and stormwater and erosion control BMPs appear to be in proper functioning condition.