

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/30/2018

Submitted Date:

07/30/2018

Document Number:

689701659

FIELD INSPECTION FORM

Loc ID 415372 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Findings:

19 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
, Caerus Piceance		COGCC.inspections@caerusoilandgas.com	Piceance inspections only
Kellerby, Shaun		shaun.kellerby@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
415326	WELL	PR	01/05/2012	GW	045-19024	N. PARACHUTE WF06A-26H26596	PR
415331	WELL	PR	02/22/2012	GW	045-19027	N. PARACHUTE WF14B-26H26596	PR
415333	WELL	PR	01/05/2012	GW	045-19028	N. PARACHUTE WF04A-35H26596	PR
415339	WELL	PR	11/25/2011	GW	045-19031	N. PARACHUTE WF03A-25H26596	PR
415340	WELL	PR	01/08/2012	GW	045-19032	N PARACHUTE WF13C-26H26596	PR
415345	WELL	PR	01/05/2012	GW	045-19035	N. Parachute WF13C-24H26 59	PR
415350	WELL	PR	02/22/2012	GW	045-19036	N. Parachute WF05C-26H26 59	PR
415356	WELL	PR	01/02/2012	GW	045-19039	N. Parachute WF05B-26H26 59	PR
415357	WELL	PR	02/07/2012	GW	045-19040	N. Parachute WF04B-25H26 59	PR
415362	WELL	PR	01/05/2012	GW	045-19042	N. PARACHUTE WF03B-35H26596	PR
415363	WELL	PR	02/22/2012	GW	045-19043	N. Parachute WF06D-26H26 59	PR
415373	WELL	PR	12/05/2011	GW	045-19045	N. PARACHUTE WF14B-24H26596	PR
415378	WELL	PR	02/07/2012	GW	045-19047	N. PARACHUTE WF04C-25H26596	PR
415379	WELL	PR	03/09/2012	GW	045-19048	N. PARACHUTE WF12B-26H26596	PR
415382	WELL	PR	03/09/2012	GW	045-19049	N. Parachute WF12A-26H26 59	PR

415387	WELL	PR	01/08/2012	GW	045-19050	N. PARACHUTE WF12C-26H26596	PR
--------	------	----	------------	----	-----------	-----------------------------	----

General Comment:

[Follow up inspection to 01/30/2018 inspection doc # 689700950](#)
[Corrective action has not been made. No emergency number on location.](#)

Location

Overall Good:

Emergency Contact Number:

Comment: Battery sign is missing emergency contact number. (Emergency contact number not found on location)

Corrective Action: Install sign to comply with Rule 210.b.

Date: 02/02/2018

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	415326	Type:	WELL	API Number:	045-19024	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	415331	Type:	WELL	API Number:	045-19027	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	415333	Type:	WELL	API Number:	045-19028	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	415339	Type:	WELL	API Number:	045-19031	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	415340	Type:	WELL	API Number:	045-19032	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	415345	Type:	WELL	API Number:	045-19035	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	415350	Type:	WELL	API Number:	045-19036	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	415356	Type:	WELL	API Number:	045-19039	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				

Facility ID: 415357	Type: WELL	API Number: 045-19040	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 415362	Type: WELL	API Number: 045-19042	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 415363	Type: WELL	API Number: 045-19043	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 415373	Type: WELL	API Number: 045-19045	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 415378	Type: WELL	API Number: 045-19047	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 415379	Type: WELL	API Number: 045-19048	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 415382	Type: WELL	API Number: 045-19049	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 415387	Type: WELL	API Number: 045-19050	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401719624	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4538026
689701661	Inspection 689701659 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4538010