

Inspected Facilities

Facility ID: 455612 Type: WELL API Number: 123-47176 Status: DG Insp. Status: DG

Complaint

Comment: [Inspection in response to complaint.](#)
[Field Inspector Assigned: Adam Kraich](#)
[Complaint Received:](#)
[Date: 7/31/2018](#)
[Complaint Contacted:](#)
[Date: 7/31/2018 Time 11:26 AM](#)
[Location #: 455340](#)
[Inspection Document #: 691300424](#)

[Nature of complaint: Noise](#)
[Field Inspector Actions:](#)
[On 7/31/2018](#)

[On 7-31-2018, I received a complaint in regards to C-Scale noise at a residence near the Rinn Valley East \(455340\) location, owned and operated by Extraction Oil & Gas.](#)

[After speaking with the residence, I set a 24 hour sound meter, and began a sound audit on 7/31/2018 @ 12:57 PM. The audit concluded on 8/3/2018 @ 09:01am. The meter was set 25' from the complainant's residence \(40.138002, 105.045853\) in accordance with rule 804.d.](#)
[The sound audit indicates an average C-Scale DB level of 67, please see audit data attached to inspection form.](#)

[COGCC noise survey results indicate noise levels exceed limits in Rule 802 \(Statewide, no exemption for low frequency issues\).](#)

[All information reviewed and site inspection information were submitted to the complaint specialist for further review.](#)

Corrective Action: [Comply with Rule 802. For low frequency issues, obtain a low frequency impact analysis and identify control measures.](#) Date: 08/11/2018

Well Drilling

Rig: Rig Name: Patterson 346 Pusher/Rig Manager: Hans Cary
 Permit Posted: Yes Access Sign: Yes

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____
 Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: _____

Drill Fluids Management:

Lined Pit: _____ Unlined Pit: _____ Closed Loop: _____ Semi-Closed Loop: _____
 Multi-Well: _____ Disposal Location: _____

Comment: [Inspection in response to complaint.](#)
[Normal drilling operations.](#)

[No odors observed on location.](#)

[No sound walls on location.](#)

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
691300426	Sound Audit	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4547082
691300427	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4547083