



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Mindy Paulek
Submission Date:	7/24/2018
Server Receive Date:	7/24/2018
Reference Number:	EIS 002
Location:	Dekay A1 and A3

Information

Name	Mindy Paulek
Date of work completion:	7/23/2018
Well Name	Dekay A1 & A3
Select State	Colorado
Work type	COGCC Inspection
Inspection Number	680602784

Special Notes: Two rock run downs were installed, and a diversion berm installed along the east edge of the well pad to direct water flow to the rock rundowns. The old well sign was removed and disposed of, and the new one secured in place. Trash was removed from the well pad. Five to six thistle plants were hand dug and removed from location. The tank pit sign was confirmed to be present. One rig anchor was confirmed to be marked and the remaining rig anchors were confirmed to be removed. No stained soils were identified on the well pad.

Photo of above state work completion



Installed Rock Rundown



Installed Rock Rundown



Install berm



Install berm



Install berm

Choose an item.