

Inspection Photos
Location Name: Bredehoft#1
Location ID: 319977



Photo#1 Production Tank & Produced water pit



Photo#2 Pumpjack/Wellhead

Inspection Photos
Location Name:Bredehoft#1
Location ID: 319977



Photo#3Equipment

Corrective Action:Weeds not controlled