

**Inspection Photo
Youberg RU 13-7
API # 045-07083
Inspection # 689301703**



Location Photo #1,



**Location Photo #2, unused piping near
edge of location**

**Inspection Photo
Youberg RU 13-7
API # 045-07083
Inspection # 689301703**




Location Photo #3, unused piping near edge of location



Location Photo #4, unused piping near edge of location



**Inspection Photo
Youberg RU 13-7
API # 045-07083
Inspection # 689301703**



Location Photo #5, unused piping near edge of location



Location Photo #6 , unused piping near edge of location

