

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/14/2018

Submitted Date:

08/14/2018

Document Number:

692600082

FIELD INSPECTION FORM

Loc ID 337905 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10112
Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC
Address: 5057 KELLER SPRINGS RD STE 650
City: ADDISON State: TX Zip: 75001

Findings:

- 15 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Beard, Alyssa		regulatory@foundationenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289563	WELL	PR	12/01/2007	GW	125-10740	STULTS 42-19	PR

General Comment:

[Routine Inspection](#)

Location			
Lease Road:			
Type	Access		
comment:	Trail through farm ground		
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Lease signs by water tank		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Metal sign by water tank		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	Metal panels around unit and wellhead		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Metal panels around meter shed and VGS		
Corrective Action:		Date:	
Equipment:			
Type: Ancillary equipment	# 2		corrective date
Comment:	Telemetry equipment and gas scrubber		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Jensen unit		
Corrective Action:		Date:	

Type: Prime Mover	# 1		
Comment:	Kohler gas engine		
Corrective Action:			Date:
Type: Vertical Separator	# 2		
Comment:	2-Vertical gas separators 50% buried by meter shed 540' NE of wellhead		
Corrective Action:			Date:
Type: Gas Meter Run	# 2		
Comment:	Shared meter run for Stults 32-19 and 42-19 540' NE of wellhead		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		39.955700,-102.336410
Comment:	Fiberglass water tank 50% buried on south side of meter shed 540' NE of wellhead				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	210bbbs
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 289563 Type: WELL API Number: 125-10740 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Casing production. Central meter run for \(Stults 42-19 and 32-19\) 1690' NE of wellhead on west side of CR BB](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Other	Pass			

Comment: [Location and access are farmed over](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT