

Inspection Photos  
Location Name: Bakers Peak Unit 2  
API: 05-081-07173



**Photo 1. Overview of location taken at entrance facing northeast.**

Inspection Photos  
Location Name: Bakers Peak Unit 2  
API: 05-081-07173



**Photo 2. No NFPA diamond on produced water tank.**



**Photo 3. 3 – 3" risers, 4 – 2" risers, and 2 – ½" risers not marked for abandonment or LOTO.**