

Inspection Photos
Location Name: Elk Springs Unit 32C-8
API: 05-081-06794



Photo 1. Overview of location taken at entrance facing east.



Photo 2. Stained soil and trash at wellhead.

Inspection Photos
Location Name: Elk Springs Unit 32C-8
API: 05-081-06794



Photo 3. Stained soil in tank battery.



Photo 4. Stained soil at tank base.