

Inspection Photos
Location Name: Elk Springs Unit 23B-8
API: 05-081-06795



Photo 1. Overview of location taken at entrance facing east.

Inspection Photos
Location Name: Elk Springs Unit 23B-8
API: 05-081-06795



Photo 2. Stained soil at tank base.



Photo 3. Stained soil at wellhead.