

B&V 24B-07-07-95
API# 05-045-22705
Inspection# 689701691



Location photo.

B&V 24B-07-07-95
API# 05-045-22705
Inspection# 689701691



Open conductor and cellar between 14B and 14A wells.



No sign for identification of undrilled well.