

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/03/2018

Submitted Date:

08/15/2018

Document Number:

689701692**FIELD INSPECTION FORM**

Loc ID 447695	Inspector Name: LONGWORTH, MIKE	On-Site Inspection <input type="checkbox"/>	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED <b>Findings:</b> 58 Number of Comments 3 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
2A Doc Num: _____			

**Operator Information:**OGCC Operator Number: 10447Name of Operator: URSA OPERATING COMPANY LLCAddress: 1600 BROADWAY ST STE 2600City: DENVER State: CO Zip: 80202**Contact Information:**

Contact Name	Phone	Email	Comment
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	<a href="#">All Inspections</a>
Pesicka, Conor		conor.pesicka@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
447698	WELL	PR	01/09/2018	GW	045-23310	BMC B 12D-18-07-95	PR
447706	WELL	PR	03/24/2018	GW	045-23318	BMC B 23D-18-07-95	PR
447707	WELL	PR	03/27/2018	GW	045-23319	BMC B 14A-18-07-95	PR
447708	WELL	PR	02/02/2018	GW	045-23320	BMC B 23B-18-07-95	PR
447709	WELL	PR	03/28/2018	GW	045-23321	BMC B 23A-18-07-95	PR
447710	WELL	PR	03/01/2018	GW	045-23322	BMC B 13B-18-07-95	PR
447711	WELL	PR	02/08/2018	GW	045-23323	BMC B 13C-18-07-95	PR
447712	WELL	PR	02/22/2018	GW	045-23324	BMC B 23C-18-07-95	PR
447713	WELL	PR	02/23/2018	GW	045-23325	BMC B 13D-18-07-95	PR
447715	WELL	PR	01/19/2018	GW	045-23327	BMC B 13A-18-07-95	PR
447716	WELL	PR	01/14/2018	GW	045-23328	BMC B 22D-18-07-95	PR
449469	WELL	PR	12/10/2017	GW	045-23477	BMC B 32B-13-07-96	PR
449470	WELL	PR	11/29/2017	GW	045-23478	BMC B 42A-13-07-96	PR
449474	WELL	PR	11/23/2017	GW	045-23479	BMC B 41C-13-07-96	PR
449475	WELL	PR	12/30/2017	GW	045-23480	BMC B 42C-13-07-96	PR
449478	WELL	PR	02/10/2018	GW	045-23481	BMC B 43B-13-07-96	PR
449479	WELL	PR	11/27/2017	GW	045-23482	BMC B 32A-13-07-96	PR
449480	WELL	PR	04/04/2018	GW	045-23483	BMC B 43A-13-07-96	PR
449482	WELL	PR	01/07/2018	GW	045-23484	BMC B 42D-13-07-96	PR
449484	WELL	PR	12/21/2017	GW	045-23485	BMC B 32C-13-07-96	PR
449485	WELL	PR	02/28/2018	GW	045-23486	BMC B 43C-13-07-96	PR
449487	WELL	PR	12/22/2017	GW	045-23487	BMC B 42B-13-07-96	PR
449489	WELL	PR	11/28/2017	GW	045-23488	BMC B 41B-13-07-96	PR

449490	WELL	PR	11/28/2017	GW	045-23489	BMC B 41D-13-07-96	PR
--------	------	----	------------	----	-----------	--------------------	----

**General Comment:**

Inspection based on complainant #200446117, #200446118, #200446119

Open conductor and cellar between 13B and 13A wells. No api # found in data base. No sign for identification of undrilled well.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	No sign for identification of undrilled well.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	10/16/2018
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 855-625-9922

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	WEEDS		
Comment:	Dead weed debri around edges of location. Dead weed debri behind heated separators.		
Corrective Action:	Comply with Rule 603.f .	Date:	08/26/2018

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Horizontal Heated Separator	# 20		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 10		
Comment:	Deadman marker have been knocked over.		

Corrective Action:	Location is within a designated setback location, mark guy line anchors per Rule 604.c. (2)Q.		Date:	08/31/2018
Type: Bird Protectors	# 12			
Comment:				
Corrective Action:			Date:	
Type: Ancillary equipment	# 5			
Comment:	Chemical containers 3 at wells and 2 at separators			
Corrective Action:			Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					
Date:					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	500 BBLS	STEEL AST		,
Comment:	Frac water storage tanks				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth					
Comment:					
Corrective Action:					
Date:					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	6	300 BBLS	STEEL AST		,
Comment:					

Corrective Action:		Date:	
--------------------	--	-------	--

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
			Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	20	500 BBLs	STEEL AST		,
Comment:	Frac water storage tanks				
Corrective Action:					
				Date:	

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:				
Corrective Action:				
			Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			
		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	447698	Type:	WELL	API Number:	045-23310	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
<b>Complaint</b>									
Comment:	Inspection based on complainant #200446117, #200446118, #200446119								
Corrective Action:						Date:			
Facility ID:	447706	Type:	WELL	API Number:	045-23318	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
<b>Complaint</b>									
Comment:	Inspection based on complainant #200446117, #200446118, #200446119								
Corrective Action:						Date:			
Facility ID:	447707	Type:	WELL	API Number:	045-23319	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
<b>Complaint</b>									
Comment:	Inspection based on complainant #200446117, #200446118, #200446119								
Corrective Action:						Date:			
Facility ID:	447708	Type:	WELL	API Number:	045-23320	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
<b>Complaint</b>									
Comment:	Inspection based on complainant #200446117, #200446118, #200446119								
Corrective Action:						Date:			
Facility ID:	447709	Type:	WELL	API Number:	045-23321	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
<b>Complaint</b>									
Comment:	Inspection based on complainant #200446117, #200446118, #200446119								
Corrective Action:						Date:			

Facility ID: 447710	Type: WELL	API Number: 045-23322	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

**Complaint**

Comment: Inspection based on complainant #200446117, #200446118, #200446119

Corrective Action:

Date:

Facility ID: 447711	Type: WELL	API Number: 045-23323	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

**Complaint**

Comment: Inspection based on complainant #200446117, #200446118, #200446119

Corrective Action:

Date:

Facility ID: 447712	Type: WELL	API Number: 045-23324	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

**Complaint**

Comment: Inspection based on complainant #200446117, #200446118, #200446119

Corrective Action:

Date:

Facility ID: 447713	Type: WELL	API Number: 045-23325	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

**Complaint**

Comment: Inspection based on complainant #200446117, #200446118, #200446119

Corrective Action:

Date:

Facility ID: 447715	Type: WELL	API Number: 045-23327	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

**Complaint**

Comment: Inspection based on complainant #200446117, #200446118, #200446119

Corrective Action:

Date:

Facility ID:	447716	Type:	WELL	API Number:	045-23328	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Producing well								
Corrective Action:						Date:			
<b><u>Complaint</u></b>									
Comment:	Inspection based on complainant #200446117, #200446118, #200446119								
Corrective Action:						Date:			
Facility ID:	449469	Type:	WELL	API Number:	045-23477	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Producing well								
Corrective Action:						Date:			
<b><u>Complaint</u></b>									
Comment:	Inspection based on complainant #200446117, #200446118, #200446119								
Corrective Action:						Date:			
Facility ID:	449470	Type:	WELL	API Number:	045-23478	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Producing well								
Corrective Action:						Date:			
<b><u>Complaint</u></b>									
Comment:	Inspection based on complainant #200446117, #200446118, #200446119								
Corrective Action:						Date:			
Facility ID:	449474	Type:	WELL	API Number:	045-23479	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Producing well								
Corrective Action:						Date:			
<b><u>Complaint</u></b>									
Comment:	Inspection based on complainant #200446117, #200446118, #200446119								
Corrective Action:						Date:			
Facility ID:	449475	Type:	WELL	API Number:	045-23480	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Producing well								
Corrective Action:						Date:			
<b><u>Complaint</u></b>									
Comment:	Inspection based on complainant #200446117, #200446118, #200446119								
Corrective Action:						Date:			



Facility ID:	449478	Type:	WELL	API Number:	045-23481	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Producing well								
Corrective Action:									Date:
<b><u>Complaint</u></b>									
Comment:	Inspection based on complainant #200446117, #200446118, #200446119								
Corrective Action:									Date:
<b><u>Producing Well</u></b>									
Comment:	Producing well								
Corrective Action:									Date:
<b><u>Complaint</u></b>									
Comment:	Inspection based on complainant #200446117, #200446118, #200446119								
Corrective Action:									Date:
<b><u>Producing Well</u></b>									
Comment:	Producing well								
Corrective Action:									Date:
<b><u>Complaint</u></b>									
Comment:	Inspection based on complainant #200446117, #200446118, #200446119								
Corrective Action:									Date:
<b><u>Producing Well</u></b>									
Comment:	Producing well								
Corrective Action:									Date:
<b><u>Complaint</u></b>									
Comment:	Inspection based on complainant #200446117, #200446118, #200446119								
Corrective Action:									Date:
<b><u>Producing Well</u></b>									
Comment:	Producing well								
Corrective Action:									Date:
<b><u>Complaint</u></b>									
Comment:	Inspection based on complainant #200446117, #200446118, #200446119								
Corrective Action:									Date:
<b><u>Producing Well</u></b>									
Comment:	Producing well								
Corrective Action:									Date:
<b><u>Complaint</u></b>									
Comment:	Inspection based on complainant #200446117, #200446118, #200446119								
Corrective Action:									Date:

Facility ID: 449485	Type: WELL	API Number: 045-23486	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

**Complaint**Comment: [Inspection based on complainant #200446117, #200446118, #200446119](#)

Corrective Action:

Date:

Facility ID: 449487	Type: WELL	API Number: 045-23487	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

**Complaint**Comment: [Inspection based on complainant #200446117, #200446118, #200446119](#)

Corrective Action:

Date:

Facility ID: 449489	Type: WELL	API Number: 045-23488	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

**Complaint**Comment: [Inspection based on complainant #200446117, #200446118, #200446119](#)

Corrective Action:

Date:

Facility ID: 449490	Type: WELL	API Number: 045-23489	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

**Complaint**Comment: [Inspection based on complainant #200446117, #200446118, #200446119](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Pass	
Gravel	Pass					
Check Dams	Pass					
Compaction	Pass					
Berms	Pass					
		Ditches	Pass			
		Compaction	Pass			
Ditches	Pass					

Comment: [Sound walls have been taken down. There's some subsidence of the closed post holes.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689701693	Inspection 689701692 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4552988">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4552988</a>