

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/15/2018

Submitted Date:

08/15/2018

Document Number:

692600094**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection ☐  
 303068 \_\_\_\_\_ Welsh, Brian \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 5057 KELLER SPRINGS RD STE 650City: ADDISON State: TX Zip: 75001**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**20 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Beard, Alyssa		regulatory@foundationenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
252382	WELL	PR	03/11/1979	GW	125-06256	STULP 1-2	PR

**General Comment:**[Routine Inspection](#)

## Location

<b>Lease Road:</b>			
Type	Access		
comment:	Two track through pasture		
Corrective Action		Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Lease sign at tank battery		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Metal sign by sump		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Metal sign by tanks		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	Metal panels around unit, wellhead, VGS and meter run		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Metal panels around pig station on north side of tank battery		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Metal panels around VGS and meter shed for pipeline		
Corrective Action:		Date:	
Type	OTHER		

Comment:	Metal panels around sump		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Tank battery is 3/4 fenced with wire panels		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 6		
Comment:	Electric panel and telemetry equipment. Telemetry equipment at meter shed for pipeline. Telemetry equipment, electric panel, electric circ pump in fiberglass shed at tank battery		
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:	Launching station on north side of tank battery		
Corrective Action:		Date:	
Type: Vertical Separator	# 4		
Comment:	1-Vertical gas separator 50% buried by meter run 1-Vertical gas separator 50% buried by meter shed for abandoned meter run 1-Vertical gas separator for Crossland and Vonderwahl bellows meters (for domestic use) next to meter shed 1-Vertical gas separator 50% buried next to meter shed for pipeline on south side of unit		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Meter run for Stulp 1-2 Old abandoned meter run and meter shed next to unit		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Progressive Cavity	# 0		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Jensen unit		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
USED OIL	1	<50 BBLS	CONCRETE SUMP/VAULT		40.078000,-102.591780	
Comment:	1500 gal slop oil sump on south side of wellhead					
Corrective Action:					Date:	

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	200 BBLs	FIBERGLASS AST		40.075590,-102.591050
Comment:	Central tank battery 940' S of wellhead on north side of CR 35				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	252382	Type:	WELL	API Number:	125-06256	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing. Casing production								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT