

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/18/2018

Submitted Date:

08/18/2018

Document Number:

689301768**FIELD INSPECTION FORM**

Loc ID 417777	Inspector Name: Holtz, Darin	On-Site Inspection <input type="checkbox"/>	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED											
2A Doc Num: _____			<b>Findings:</b> 26 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested											
<b>Operator Information:</b> OGCC Operator Number: <u>10447</u> Name of Operator: <u>URSA OPERATING COMPANY LLC</u> Address: <u>1600 BROADWAY ST STE 2600</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>														
<b>Contact Information:</b>														
<table border="1" style="width:100%"> <tr> <th>Contact Name</th> <th>Phone</th> <th>Email</th> <th>Comment</th> </tr> <tr> <td>Knudson, Dwayne</td> <td>970-456-3335</td> <td>dknudson@ursaresources.com</td> <td><a href="#">All Inspections</a></td> </tr> <tr> <td>Kellerby, Shaun</td> <td></td> <td>shaun.kellerby@state.co.us</td> <td></td> </tr> </table>				Contact Name	Phone	Email	Comment	Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	<a href="#">All Inspections</a>	Kellerby, Shaun		shaun.kellerby@state.co.us
Contact Name	Phone	Email	Comment											
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	<a href="#">All Inspections</a>											
Kellerby, Shaun		shaun.kellerby@state.co.us												

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
417823	WELL	PR	01/17/2012	GW	045-19639	Frei A21	PR
417824	WELL	PR	01/17/2012	GW	045-19640	Frei A11	PR
417825	WELL	PR	01/24/2014	GW	045-19641	Frei A9	PR
417829	WELL	PR	10/28/2011	GW	045-19642	Frei A16	PR
419521	WELL	PR	06/11/2014	LO	045-19945	Frei A20	PR
419525	WELL	PR	09/24/2014	LO	045-19947	Frei A14	PR
419527	WELL	PR	07/21/2014	LO	045-19949	Frei A12	PR
419529	WELL	PR	06/15/2014	LO	045-19951	Frei A18	PR
419530	WELL	DG	02/02/2014	LO	045-19952	Frei A4	DG
419532	WELL	PR	06/24/2015	LO	045-19953	Frei A23	PR
419534	WELL	DG	06/08/2016	LO	045-19954	Frei A2	DG
419535	WELL	PR	06/08/2014	OW	045-19955	Frei A19	PR
419539	WELL	DG	01/28/2014	LO	045-19958	Frei A1	DG
419540	WELL	DG	02/01/2014	LO	045-19959	Frei A3	DG
419541	WELL	PR	06/22/2015	LO	045-19960	Frei A24	PR
419542	WELL	PR	09/24/2014	LO	045-19961	Frei A10	PR

**General Comment:**

This inspection is complaint related. Ref# 200446147.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

Emergency Contact Number:

Comment: 1-855-625-9922

Corrective Action:

Date:

**Good Housekeeping:**

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	
Type	TRASH		
Comment:			
Corrective Action:		Date:	
Type	WEEDS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Livestock gates		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 1		
Comment:	trailer mounted chemical unit		
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 2		
Comment:	Mark as required		
Corrective Action:		Date:	

Type: Bird Protectors	# 11		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 16		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 12		
Comment:			
Corrective Action:			Date:
Type: Flow Line	# 1		
Comment:	water flowlines		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	300 BBLs	HEATED STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	300 BBLs	HEATED STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					

Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	3	300 BBLs	STEEL AST		,	
Comment: Centralized battery						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	YES		
Comment:	A-16, 045-19642 A-11, 045-19640 A-10, 045-19961 A-21, 045-19639 A-24, 045-19960 Bradenhead gas is tied into sales line		
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	417823	Type:	WELL	API Number:	045-19639	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	417824	Type:	WELL	API Number:	045-19640	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	417825	Type:	WELL	API Number:	045-19641	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	417829	Type:	WELL	API Number:	045-19642	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	419521	Type:	WELL	API Number:	045-19945	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	419525	Type:	WELL	API Number:	045-19947	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	419527	Type:	WELL	API Number:	045-19949	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			

**Complaint**

Comment: Ref # 200446147, Stayed on location for 2 hours, as the wells cycled on/off for production one well stood out with a high pitched noise, A-12. It lasted approximately 6-7 minutes until well shut in. Other wells made a high pitched noise that only lasted a couple minutes and dissipated. No other noises could be heard.

Corrective Action:

Date:

Facility ID: 419529 Type: WELL API Number: 045-19951 Status: PR Insp. Status: PR

**Producing Well**

Comment: Well Producing on plunger lift

Corrective Action:

Date:

Facility ID: 419530 Type: WELL API Number: 045-19952 Status: DG Insp. Status: DG

**Well Drilling**

**Rig:** Rig Name: \_\_\_\_\_ Pusher/Rig Manager: \_\_\_\_\_  
Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_

Comment: Conductor casing installed, no drill rig on location.

Corrective Action:

Date:

Facility ID: 419532 Type: WELL API Number: 045-19953 Status: PR Insp. Status: PR

**Producing Well**

Comment: Well Producing on plunger lift

Corrective Action:

Date:

Facility ID: 419534 Type: WELL API Number: 045-19954 Status: DG Insp. Status: DG

**Well Drilling**

**Rig:** Rig Name: \_\_\_\_\_ Pusher/Rig Manager: \_\_\_\_\_  
Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_

Comment: Conductor casing installed, no drill rig on location.

Corrective Action:		Date:	
--------------------	--	-------	--

Facility ID:	419535	Type:	WELL	API Number:	045-19955	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**

Comment:	Well Producing on plunger lift		
Corrective Action:		Date:	

Facility ID:	419539	Type:	WELL	API Number:	045-19958	Status:	DG	Insp. Status:	DG
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Well Drilling**

<b>Rig:</b>	Rig Name:	Pusher/Rig Manager:
	Permit Posted:	Access Sign:

**Well Control Equipment:**

Pipe Ram:	Blind Ram:	Hydril Type:
Pressure Test BOP:	Test Pressure PSI:	Safety Plan:

**Drill Fluids Management:**

Lined Pit:	Unlined Pit:	Closed Loop:	Semi-Closed Loop:
Multi-Well:	Disposal Location:		
Comment:	Conductor casing installed, no drill rig on location.		
Corrective Action:		Date:	

Facility ID:	419540	Type:	WELL	API Number:	045-19959	Status:	DG	Insp. Status:	DG
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Well Drilling**

<b>Rig:</b>	Rig Name:	Pusher/Rig Manager:
	Permit Posted:	Access Sign:

**Well Control Equipment:**

Pipe Ram:	Blind Ram:	Hydril Type:
Pressure Test BOP:	Test Pressure PSI:	Safety Plan:

**Drill Fluids Management:**

Lined Pit:	Unlined Pit:	Closed Loop:	Semi-Closed Loop:
Multi-Well:	Disposal Location:		
Comment:	Conductor casing installed. no drill rig in location		
Corrective Action:		Date:	

Facility ID:	419541	Type:	WELL	API Number:	045-19960	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**

Comment:	Well Producing on plunger lift		
Corrective Action:		Date:	

Facility ID:	419542	Type:	WELL	API Number:	045-19961	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well			
Comment:	Well Producing on plunger lift		
Corrective Action:		Date:	



## Environmental

### Spill/Remediation:

Comment:

Corrective  
Action:

Date:

Emission Control Burner (ECB): YES

Comment: 2 units on location

Pilot: ON

Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				
Gravel						
Slope Roughening						
		Compaction				
Berms						
				Material Handling And Spill Prevention		

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689301769	Inspection photo 689301769	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4555390">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4555390</a>