

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/17/2018

Submitted Date:

08/17/2018

Document Number:

689701720**FIELD INSPECTION FORM**

Loc ID 324411	Inspector Name: LONGWORTH, MIKE	On-Site Inspection <input type="checkbox"/>	<b>Status Summary:</b> <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
2A Doc Num: _____			<b>Findings:</b> 7 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
<b>Operator Information:</b>			
OGCC Operator Number: <u>96850</u>			
Name of Operator: <u>TEP ROCKY MOUNTAIN LLC</u>			
Address: <u>PO BOX 370</u>			
City: <u>PARACHUTE</u>	State: <u>CO</u>	Zip: <u>81635</u>	

**Contact Information:**

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	
Pesicka, Conor		conor.pesicka@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
290472	WELL	PR	05/07/2007	GW	045-14112	CHEVRON TR 43-32-597	PR
451172	WELL	XX	06/23/2017		045-23576	CHEVRON TR 34-32-597	ND
451173	WELL	XX	06/23/2017		045-23577	CHEVRON TR 13-33-597	ND
451174	WELL	XX	06/23/2017		045-23578	CHEVRON TR 533-32-597	ND
451175	WELL	XX	06/23/2017		045-23579	CHEVRON TR 432-32-597	ND
451176	WELL	XX	06/23/2017		045-23580	CHEVRON TR 414-33-597	ND
451177	WELL	XX	06/23/2017		045-23581	CHEVRON TR 334-32-597	ND
451178	WELL	XX	06/23/2017		045-23582	CHEVRON TR 14-33-597	ND
451179	WELL	XX	06/23/2017		045-23583	CHEVRON TR 534-32-597	ND
451180	WELL	XX	06/23/2017		045-23584	CHEVRON TR 514-33-597	ND
451181	WELL	XX	06/23/2017		045-23585	CHEVRON TR 32-32-597	ND
451182	WELL	XX	06/23/2017		045-23586	CHEVRON TR 413-33-597	ND
451183	WELL	XX	06/23/2017		045-23587	CHEVRON TR 512-33-597	ND
451184	WELL	XX	06/23/2017		045-23588	CHEVRON TR 434-32-597	ND
451185	WELL	XX	06/23/2017		045-23589	CHEVRON TR 314-33-597	ND
451186	WELL	XX	06/23/2017		045-23590	CHEVRON TR 513-33-597	ND
451187	WELL	XX	06/23/2017		045-23591	CHEVRON TR 433-32-597	ND
451188	WELL	XX	06/23/2017		045-23592	CHEVRON TR 532-32-597	ND
451189	WELL	XX	06/23/2017		045-23593	CHEVRON TR 333-32-597	ND
451190	WELL	XX	06/23/2017		045-23594	CHEVRON TR 33-32-597	ND
451191	WELL	XX	06/23/2017		045-23595	CHEVRON TR 313-33-597	ND

**General Comment:**

Follow up inspection to 6/22/2018 inspection 689701512  
Corrective action have been completed.

**Location**Overall Good: ☐**Signs/Marker:**

Type	CONTAINERS		
Comment:	Installed		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Installed		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Installed		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Volume fixed on label		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-285-9377

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	290472	Type:	WELL	API Number:	045-14112	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well							Date:	
Corrective Action:								Date:	
Facility ID:	451172	Type:	WELL	API Number:	045-23576	Status:	XX	Insp. Status:	ND
Facility ID:	451173	Type:	WELL	API Number:	045-23577	Status:	XX	Insp. Status:	ND
Facility ID:	451174	Type:	WELL	API Number:	045-23578	Status:	XX	Insp. Status:	ND
Facility ID:	451175	Type:	WELL	API Number:	045-23579	Status:	XX	Insp. Status:	ND
Facility ID:	451176	Type:	WELL	API Number:	045-23580	Status:	XX	Insp. Status:	ND
Facility ID:	451177	Type:	WELL	API Number:	045-23581	Status:	XX	Insp. Status:	ND
Facility ID:	451178	Type:	WELL	API Number:	045-23582	Status:	XX	Insp. Status:	ND
Facility ID:	451179	Type:	WELL	API Number:	045-23583	Status:	XX	Insp. Status:	ND
Facility ID:	451180	Type:	WELL	API Number:	045-23584	Status:	XX	Insp. Status:	ND
Facility ID:	451181	Type:	WELL	API Number:	045-23585	Status:	XX	Insp. Status:	ND
Facility ID:	451182	Type:	WELL	API Number:	045-23586	Status:	XX	Insp. Status:	ND
Facility ID:	451183	Type:	WELL	API Number:	045-23587	Status:	XX	Insp. Status:	ND
Facility ID:	451184	Type:	WELL	API Number:	045-23588	Status:	XX	Insp. Status:	ND
Facility ID:	451185	Type:	WELL	API Number:	045-23589	Status:	XX	Insp. Status:	ND
Facility ID:	451186	Type:	WELL	API Number:	045-23590	Status:	XX	Insp. Status:	ND
Facility ID:	451187	Type:	WELL	API Number:	045-23591	Status:	XX	Insp. Status:	ND
Facility ID:	451188	Type:	WELL	API Number:	045-23592	Status:	XX	Insp. Status:	ND

Facility ID: 451189	Type: WELL	API Number: 045-23593	Status: XX	Insp. Status: ND
Facility ID: 451190	Type: WELL	API Number: 045-23594	Status: XX	Insp. Status: ND
Facility ID: 451191	Type: WELL	API Number: 045-23595	Status: XX	Insp. Status: ND

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689701721	Inspection 689701720 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4555406">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4555406</a>