

Inspection Photos
Well Name: Oxbow 18-1E
Location ID: 312634



Photo 1. Stormwater controls installed on edge of location.



Photo 2. Road graded and bar ditch cleaned.

Inspection Photos
Well Name: Oxbow 18-1E
Location ID: 312634



Photo 3. Halogeton still present in roadway.



Photo 4. Halogeton still present in roadway.