

**Inspection Photo
Federal 6/7-14-21
API # 045-21180
Inspection # 689301749**



Location Photo #1,



Location Photo #2,

**Inspection Photo
Federal 6/7-14-21
API # 045-21180
Inspection # 689301749**



Location Photo #3,



**Location Photo #4, Stained rock in
containment area.**

Inspection Photo
Federal 6/7-14-21
API # 045-21180
Inspection # 689301749



Location Photo #5, Stained rock in containment area.



Location Photo #6, Stained rock in containment area.

**Inspection Photo
Federal 6/7-14-21
API # 045-21180
Inspection # 689301749**




Location Photo #7, Stained rock in containment area.



Location Photo #8, Stained rock in containment area.

**Inspection Photo
Federal 6/7-14-21
API # 045-21180
Inspection # 689301749**



Location Photo #9, Stained rock in containment area.



Location Photo #10, Stained rock in containment area.

Inspection Photo
Federal 6/7-14-21
API # 045-21180
Inspection # 689301749



**Location Photo #11, Stained rock in
containment area.**