

Inspection Photo
Quarter Circle 43-33H
API # 045-06782
Inspection # 689301770



Location Photo #1,



Location Photo #2,

Inspection Photo
Quarter Circle 43-33H
API # 045-06782
Inspection # 689301770



Location Photo #3,



**Location Photo #4, Weeds still not
addressed on location.**

Inspection Photo
Quarter Circle 43-33H
API # 045-06782
Inspection # 689301770



Location Photo #5, Weeds still not addressed on location.



Location Photo #6, Weeds still not addressed on location.

Inspection Photo
Quarter Circle 43-33H
API # 045-06782
Inspection # 689301770



Location Photo #7, Weeds still not addressed on location.



Location Photo #8, Weeds still not addressed on location.



Inspection Photo
Quarter Circle 43-33H
API # 045-06782
Inspection # 689301770



Location Photo #9, Debris removed from location



Location Photo #10, Debris removed from location