

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/21/2018

Submitted Date:

08/21/2018

Document Number:

689301784**FIELD INSPECTION FORM**

Loc ID 335549	Inspector Name: Holtz, Darin	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 18 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: <u>10447</u> Name of Operator: <u>URSA OPERATING COMPANY LLC</u> Address: <u>1600 BROADWAY ST STE 2600</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>				

Contact Information:

Contact Name	Phone	Email	Comment
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289821	WELL	PR	10/12/2007	GW	045-13882	GENTRY B3	PR
289849	WELL	PR	03/30/2012	GW	045-13887	GENTRY B1	PR
289850	WELL	PR	08/10/2012	GW	045-13886	Gentry B2	PR
290738	WELL	PR	05/01/2018	GW	045-14188	GENTRY B10	PR
290739	WELL	PR	05/05/2014	GW	045-14187	GENTRY B11	PR
294757	WELL	PR	12/01/2012	GW	045-15584	Gentry B7	PR
294758	WELL	PR	06/20/2012	GW	045-15585	Gentry B9	PR
294759	WELL	PR	06/22/2012	GW	045-15586	Gentry B8	PR
294760	WELL	XX	04/02/2018	LO	045-15587	Gentry B12	ND
294761	WELL	XX	04/02/2018	LO	045-15588	Gentry B13	ND
294762	WELL	PR	08/10/2012	GW	045-15589	Gentry B14	PR

General Comment:[Routine Field Inspection](#)

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action:		Date:	

Overall Good: ☒

Emergency Contact Number:

Comment: 1-855-625-9922

Corrective Action:

Date:

Good Housekeeping:

Type	WEEDS		
Comment:			
Corrective Action:		Date:	
Type	TRASH		
Comment:			
Corrective Action:		Date:	
Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Livestock gates		
Corrective Action:		Date:	

Equipment:

Type: Bird Protectors	# 7		corrective date
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:	Water line		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 9		
Comment:			
Corrective Action:		Date:	

Type: Plunger Lift	# 9		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 5		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	3	300 BBLs	STEEL AST		,	
Comment:	Centralized battery					
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Inadequate	
Comment:	Containment walls damaged, see photo				
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 605.a.(4).				Date: 09/21/2018

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	289821	Type:	WELL	API Number:	045-13882	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	289849	Type:	WELL	API Number:	045-13887	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	289850	Type:	WELL	API Number:	045-13886	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	290738	Type:	WELL	API Number:	045-14188	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	290739	Type:	WELL	API Number:	045-14187	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	294757	Type:	WELL	API Number:	045-15584	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	294758	Type:	WELL	API Number:	045-15585	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	294759	Type:	WELL	API Number:	045-15586	Status:	PR	Insp. Status:	PR

Producing Well

Comment: Well Producing on plunger lift

Corrective Action:

Date:

Facility ID: 294760 Type: WELL API Number: 045-15587 Status: XX Insp. Status: ND

Well Drilling

Rig: Rig Name: _____ Pusher/Rig Manager: _____
 Permit Posted: _____ Access Sign: _____

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____
 Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: _____

Drill Fluids Management:

Lined Pit: _____ Unlined Pit: _____ Closed Loop: _____ Semi-Closed Loop: _____
 Multi-Well: _____ Disposal Location: _____

Comment: Conductor casing installed, no drill rig on site

Corrective Action:

Date:

Facility ID: 294761 Type: WELL API Number: 045-15588 Status: XX Insp. Status: ND

Well Drilling

Rig: Rig Name: _____ Pusher/Rig Manager: _____
 Permit Posted: _____ Access Sign: _____

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____
 Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: _____

Drill Fluids Management:

Lined Pit: _____ Unlined Pit: _____ Closed Loop: _____ Semi-Closed Loop: _____
 Multi-Well: _____ Disposal Location: _____

Comment: Conductor casing installed, no drill rig on site

Corrective Action:

Date:

Facility ID: 294762 Type: WELL API Number: 045-15589 Status: PR Insp. Status: PR

Producing Well

Comment: Well Producing on plunger lift

Corrective Action:

Date:

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): YES	
Comment:	
Pilot: ON	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
Ditches						
Compaction						
		Gravel				
		Compaction				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689301785	Inspection photo 689301785	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4558255