

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/03/2018

Submitted Date:

08/15/2018

Document Number:

689701691**FIELD INSPECTION FORM**

Loc ID 440634	Inspector Name: LONGWORTH, MIKE	On-Site Inspection <input type="checkbox"/>	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 53 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
2A Doc Num: _____			

Operator Information:			
OGCC Operator Number: <u>10447</u>			
Name of Operator: <u>URSA OPERATING COMPANY LLC</u>			
Address: <u>1600 BROADWAY ST STE 2600</u>			
City: <u>DENVER</u>	State: <u>CO</u>	Zip: <u>80202</u>	

Contact Information:

Contact Name	Phone	Email	Comment
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	All Inspections
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
440632	WELL	PR	05/28/2017	LO	045-22705	B&V 24B-07-07-95	PR
440633	WELL	PR	05/25/2017	LO	045-22706	B&V 14B-07-07-95	PR
440635	WELL	PR	09/01/2017	LO	045-22707	B&V 23C-07-07-95	PR
440636	WELL	PR	08/01/2017	LO	045-22708	B&V 23B-07-07-95	PR
440637	WELL	PR	06/01/2017	LO	045-22709	B&V 41A-13-07-96	PR
440638	WELL	PR	07/01/2017	LO	045-22710	B&V 23A-07-07-95	PR
440639	WELL	PR	06/25/2017	LO	045-22711	B&V 21A-18-07-95	PR
440640	WELL	PR	09/01/2017	LO	045-22712	B&V 13C-07-07-95	PR
440641	WELL	PR	06/26/2017	LO	045-22713	B&V 11A-18-07-95	PR
440642	WELL	PR	06/14/2017	LO	045-22714	B&V 24D-07-07-95	PR
440643	WELL	PR	06/13/2017	LO	045-22715	B&V 14D-07-07-95	PR
440644	WELL	PR	05/23/2017	LO	045-22716	B&V 24A-07-07-95	PR
440645	WELL	PR	10/01/2017	LO	045-22717	B&V 13D-07-07-95	PR
440646	WELL	PR	07/01/2017	LO	045-22718	B&V 13A-07-07-95	PR
440647	WELL	PR	08/01/2017	LO	045-22719	B&V 13B-07-07-95	PR
440648	WELL	PR	06/05/2017	LO	045-22720	B&V 14C-07-07-95	PR
440649	WELL	PR	05/20/2017	LO	045-22721	B&V 14A-07-07-95	PR
440650	WELL	PR	06/06/2017	LO	045-22722	B&V 24C-07-07-95	PR
440651	WELL	PR	10/01/2017	LO	045-22723	B&V 23D-07-07-95	PR
441596	WELL	PR	09/01/2017	LO	045-22843	B&V 33C-07-07-95	PR
441597	WELL	PR	08/01/2017	LO	045-22844	B&V 33B-07-07-95	PR
441598	WELL	PR	06/01/2017	LO	045-22845	B&V 11B-18-07-95	PR
441599	WELL	PR	10/01/2017	LO	045-22846	B&V 33D-07-07-95	PR

441600	WELL	PR	07/01/2017	LO	045-22847	B&V 33A-07-07-95	PR
--------	------	----	------------	----	-----------	------------------	----

General Comment:

Inspection based on complainant #200446117, #200446118, #200446119
Open conductor and cellar between 14B and 14A wells. No api # found in data base. No sign for identification of undrilled well.

LocationOverall Good: ☒

Signs/Marker:			
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	No sign for identification of undrilled well.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	10/16/2018
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 855-625-9922

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bird Protectors	# 12		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 7		
Comment:	Chemical containers 3 at wells 4 at separators.		
Corrective Action:		Date:	
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 20		

Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 20		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	8	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				

Venting:

Yes/No	NO		
--------	----	--	--

Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected Facilities									
Facility ID:	440632	Type:	WELL	API Number:	045-22705	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Complaint									
Comment:	Inspection based on complainant #200446117, #200446118, #200446119								
Corrective Action:						Date:			
Facility ID:	440633	Type:	WELL	API Number:	045-22706	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Complaint									
Comment:	Inspection based on complainant #200446117, #200446118, #200446119								
Corrective Action:						Date:			
Facility ID:	440635	Type:	WELL	API Number:	045-22707	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Complaint									
Comment:	Inspection based on complainant #200446117, #200446118, #200446119								
Corrective Action:						Date:			
Facility ID:	440636	Type:	WELL	API Number:	045-22708	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Complaint									
Comment:	Inspection based on complainant #200446117, #200446118, #200446119								
Corrective Action:						Date:			
Facility ID:	440637	Type:	WELL	API Number:	045-22709	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Complaint									
Comment:	Inspection based on complainant #200446117, #200446118, #200446119								
Corrective Action:						Date:			

Facility ID: 440638	Type: WELL	API Number: 045-22710	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Complaint

Comment: Inspection based on complainant #200446117, #200446118, #200446119

Corrective Action:

Date:

Facility ID: 440639	Type: WELL	API Number: 045-22711	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Complaint

Comment: Inspection based on complainant #200446117, #200446118, #200446119

Corrective Action:

Date:

Facility ID: 440640	Type: WELL	API Number: 045-22712	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Complaint

Comment: Inspection based on complainant #200446117, #200446118, #200446119

Corrective Action:

Date:

Facility ID: 440641	Type: WELL	API Number: 045-22713	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Complaint

Comment: Inspection based on complainant #200446117, #200446118, #200446119

Corrective Action:

Date:

Facility ID: 440642	Type: WELL	API Number: 045-22714	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Complaint

Comment: Inspection based on complainant #200446117, #200446118, #200446119

Corrective Action:

Date:

Facility ID:	440643	Type:	WELL	API Number:	045-22715	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:									Date:
<u>Complaint</u>									
Comment:	Inspection based on complainant #200446117, #200446118, #200446119								
Corrective Action:									Date:
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:									Date:
<u>Complaint</u>									
Comment:	Inspection based on complainant #200446117, #200446118, #200446119								
Corrective Action:									Date:
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:									Date:
<u>Complaint</u>									
Comment:	Inspection based on complainant #200446117, #200446118, #200446119								
Corrective Action:									Date:
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:									Date:
<u>Complaint</u>									
Comment:	Inspection based on complainant #200446117, #200446118, #200446119								
Corrective Action:									Date:
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:									Date:
<u>Complaint</u>									
Comment:	Inspection based on complainant #200446117, #200446118, #200446119								
Corrective Action:									Date:
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:									Date:
<u>Complaint</u>									
Comment:	Inspection based on complainant #200446117, #200446118, #200446119								
Corrective Action:									Date:

Facility ID:	440648	Type:	WELL	API Number:	045-22720	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:									Date:
<u>Complaint</u>									
Comment:	Inspection based on complainant #200446117, #200446118, #200446119								
Corrective Action:									Date:
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:									Date:
<u>Complaint</u>									
Comment:	Inspection based on complainant #200446117, #200446118, #200446119								
Corrective Action:									Date:
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:									Date:
<u>Complaint</u>									
Comment:	Inspection based on complainant #200446117, #200446118, #200446119								
Corrective Action:									Date:
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:									Date:
<u>Complaint</u>									
Comment:	Inspection based on complainant #200446117, #200446118, #200446119								
Corrective Action:									Date:
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:									Date:
<u>Complaint</u>									
Comment:	Inspection based on complainant #200446117, #200446118, #200446119								
Corrective Action:									Date:
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:									Date:
<u>Complaint</u>									
Comment:	Inspection based on complainant #200446117, #200446118, #200446119								
Corrective Action:									Date:

Facility ID: 441597	Type: WELL	API Number: 045-22844	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing WellComment: [Producing well](#)

Corrective Action:

Date:

ComplaintComment: [Inspection based on complainant #200446117, #200446118, #200446119](#)

Corrective Action:

Date:

Facility ID: 441598	Type: WELL	API Number: 045-22845	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing WellComment: [Producing well](#)

Corrective Action:

Date:

ComplaintComment: [Inspection based on complainant #200446117, #200446118, #200446119](#)

Corrective Action:

Date:

Facility ID: 441599	Type: WELL	API Number: 045-22846	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing WellComment: [Producing well](#)

Corrective Action:

Date:

ComplaintComment: [Inspection based on complainant #200446117, #200446118, #200446119](#)

Corrective Action:

Date:

Facility ID: 441600	Type: WELL	API Number: 045-22847	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing WellComment: [Producing well](#)

Corrective Action:

Date:

ComplaintComment: [Inspection based on complainant #200446117, #200446118, #200446119](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
		Paving	Pass			
				Material Handling And Spill Prevention	Pass	
Ditches	Pass					
Gravel	Pass					
Berms	Pass					
Waddles	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401734667	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4552994
689701714	Inspection 689701691 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4552987