

Inspection Photos
Location Name: Moffat 26-12-89 SWD #1
Location ID: 333336



Photo 1. Overview of location taken at entrance facing west.



Photo 2. Tanks with no berm.

Inspection Photos
Location Name: Moffat 26-12-89 SWD #1
Location ID: 333336



Photo 3. Same sign at both wellheads.



Photo 4. Same sign at both wellheads.

Inspection Photos
Location Name: Moffat 26-12-89 SWD #1
Location ID: 333336



Photo 5. Unmarked riser; noxious and annual weeds.



Photo 6. Unmarked risers.