

Final Reclamation Inspection

August 21, 2018

Operator: PDC ENERGY INC - 69175

API: 05-123-19740

Inspection Document #: 682403893

Weld County, CO

NESE Section 20 T2N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: SUCCO #43-20
API: 05-123-19740



Photo 1. Photo taken from the well location, facing East. Well location will remain in-process as weedy, annual vegetation was observed. It is unclear whether or not the well location is within corn or alfalfa crop.

Inspection Photos
Location Name: SUCCO #43-20
API: 05-123-19740



Photo 2. Reference photo taken from the well location, facing South. Photo illustrates the adjacent corn crop.



Photo 3. Reference photo taken from the well location, facing Southeast. Photo illustrates the adjacent alfalfa crop.