

Inspection Photos
Location Name:Nile D Sand Unit
Location ID: 150207



Photo#1 Location/(4) 400bbl water tanks/(1)450bbl crude oil and water/(4)300bbls production tanks




Photo#2 Propane tank/(2) ECDs/Corrective Action Unused Equipment

Inspection Photos
Location Name:Nile D Sand Unit
Location ID: 150207



Photo#3 Corrective Action Fluid leaking on the ground inside containment. Called Operator right away



Photo#4 Same area as picture #3

Inspection Photos
Location Name:Nile D Sand Unit
Location ID: 150207



Photo#5 Cleaned up area from pictures **3&4**



Photo#6 **Corrective Action. Containment tank needs to be bottomed out.**

Inspection Photos
Location Name:Nile D Sand Unit
Location ID: 150207



Photo#7 Corrective Action/Bottom of tank is leaking from connection



Photo#8 Corrective action stained soil

Inspection Photos
Location Name:Nile D Sand Unit
Location ID: 150207



Photo#9 Corrective Action Stained soil



Photo#10 Corrective Action bottom of tank is leaking from connection