

**GM 23-34**  
**API# 05-045-07711**  
**Inspection# 689701744**



**Location photo.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



**GM 23-34**  
**API# 05-045-07711**  
**Inspection# 689701744**



**Weeds and weed debris in drain basin.**

**GM 23-34**  
**API# 05-045-07711**  
**Inspection# 689701744**



**Pooling of storm water.**



**GM 23-34**  
**API# 05-045-07711**  
**Inspection# 689701744**



**Weeds between separators and tank battery and lumber debris.**



**GM 23-34**  
**API# 05-045-07711**  
**Inspection# 689701744**



**Weeds covering location**



**GM 23-34**  
**API# 05-045-07711**  
**Inspection# 689701744**



**Sediment build up and ruts in road ditch**



**Washing of road ditch.**