

S. Parachute TBI 36-23
API# 05-045-007734
Inspection# 689701743



the public road used to access the site not posted



the public road used to access the site not posted

S. Parachute TBI 36-23
API# 05-045-007734
Inspection# 689701743



the public road used to access the site not posted



the public road used to access the site not posted

S. Parachute TBI 36-23
API# 05-045-007734
Inspection# 689701743



the public road used to access the site not posted



the public road used to access the site not posted

S. Parachute TBI 36-23
API# 05-045-007734
Inspection# 689701743



Weeds on location.

S. Parachute TBI 36-23
API# 05-045-007734
Inspection# 689701743



Weeds on location.



Weeds on location.

S. Parachute TBI 36-23
API# 05-045-007734
Inspection# 689701743



Weeds in tank berm.

S. Parachute TBI 36-23
API# 05-045-007734
Inspection# 689701743



Unused waddle.



Gas line sign not in use.

S. Parachute TBI 36-23
API# 05-045-007734
Inspection# 689701743



Unmarked deadmen.