

Inspection Photos
Location Name: Federal 11-90-24 #1
API: 05-051-06057



Stained equipment and wet soil surrounding well head.



Stained soil has been removed from near drop out tank and placed on temporary lined storage area.

Inspection Photos
Location Name: Federal 11-90-24 #1
API: 05-051-06057



Stained soil temporarily stored on site in lined containment area.



Federal 11-90-24 #1 well head with white residue and wet soil.