

**Inspection Photos (08-13-2018)**  
**Location Name: Rider Family Trust #1**  
**Facility ID: 10507, REM: 11300**



**Backhoe excavating near the former partially-buried vessel**



**Close up of backhoe bucket lifting impacted soil from excavation**



**Inspection Photos (08-13-2018)**  
**Location Name: Rider Family Trust #1**  
**Facility ID: 10507, REM: 11300**



**Impacted soils in the excavation**



**Ground water infiltrating the excavation**



**Inspection Photos (08-13-2018)**  
**Location Name: Rider Family Trust #1**  
**Facility ID: 10507, REM: 11300**



**Sample collection for field screening**



**Impacted soil stock piled on liner**